

LOT LOCATION:
 CUSTOMER #: 129604
 UNIT# 14

169933

Peterbilt of Utah

BLUE ROCK LLC
 47 W FIRECLAY AVE APT 326
 MURRAY, UT 84107
 HOME:801-699-3149 CONT:801-699-3149
 BUS: CELL:

INVOICE

1910 South 5500 West
 Salt Lake City, Utah 84104

PAGE 1

P.O. Box 27634
 Salt Lake City, Utah 84127
 Phone (801) 486-8781

SERVICE ADVISOR: 1033 CORY LEONARD

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
CREAM	14	KENWORTH W900	1XKWD49X9EJ412350		636093/636093	T14

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP13 DD			23:00 11JAN22	CASH	0.00	CASH	13JAN22

R.O. OPENED	READY	OPTIONS:
11JAN22	13JAN22	DLR:P250 ENG:79687791 TRN:S1037837

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CONTACT TRISTAN FOR AUTH 801-699-3149 (BLUE ROCK)
 IF CONTACT TRISTAN FOR AUTH 801-699-3149 (BLUE ROCK)
 999 IP04 (N/C)

B CUSTOMER STATES THE POWER STEERING IS INOP INTERMITTENTLY, ADVISE
 DOESN'T MATTER IF OIL IS HOT OR COLD
 PS POWER STEERING REPAIRS
 2181 C
 2560 C

					795.00	795.00	
1	TAS65219	MAN	GEAR-STEERING	REMAN	1049.60	839.68	839.68
			CORE CHARGE	C		400.00	400.00
2	J200	O	RINGS		2.61	2.38	4.76
1	Q79699	FLG	GASKET		5.29	4.81	4.81
1	87904M		FILTER-POWER	STEERING	30.32	27.59	27.59
2	HE2308		HOSE-PUSH ON	#12X25' RBR	5.87	5.34	10.68
2	9210TRP		CLAMP-HOSE	W/LINER #10	2.48	2.26	4.52
3	123130EXX		MOBIL ATF	D/M CASE 6X1QT	5.86	5.33	15.99
1	J200	O	RINGS		2.61	2.38	2.38
2	HE2277		HOSE-PUSH ON	#8X25' RBR C	2.90	2.64	5.28
2	32007		HOSE CLAMP		4.62	4.20	8.40
-1	TAS65219	MAN	CORE	RETURN	400.00	400.00	-400.00

636093
 2181 1-11-22 CUSTOMER COMPLAINT OF THE POWER STEERING INOP
 INTERMITTENTLY. PULLED THE TRUCK IN AND INSPECTED THE POWER STEERING
 RESERVOIR. CHECKED AND FOUND THAT THE RESERVOIR WAS RIGHT AT THE ADD
 MARK ON THE COLD SIDE. INSPECTED THE HOSES AND FOUND THAT THE SMALLER
 HOSE GOING TO THE POWER STEERING BOX WAS A SILICONE STYLE OF HOSE WHICH
 WAS SEEPING FROM THE HOSE. HOOKED THE POWER STEERING TESTER ONTO THE
 TRUCK AND TESTED THE POWER STEERING SYSTEM. CHECKED AND FOUND THAT THE
 POWER STEERING PUMP DID TEST GOOD. TESTED THE STEERING BOX AND FOUND
 THAT WHILE TURNING RIGHT THAT THE BOX PRESSURE WAS ONLY GOING TO 1000
 PSI WHICH IS ON THE LOWER SIDE. BOX IS FAILING INTERMITTENTLY AND

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER
 The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

LOT LOCATION:
 CUSTOMER #: 129604
 UNIT# 14

169933

Peterbilt of Utah

BLUE ROCK LLC
 47 W FIRECLAY AVE APT 326
 MURRAY, UT 84107
 HOME:801-699-3149 CONT:801-699-3149
 BUS: CELL:

INVOICE

1910 South 5500 West
 Salt Lake City, Utah 84104

PAGE 2

P.O. Box 27634
 Salt Lake City, Utah 84127
 Phone (801) 486-8781

SERVICE ADVISOR: 1033 CORY LEONARD

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
CREAM	14	KENWORTH W900	1XKWD49X9EJ412350		636093/636093	T14	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP13 DD			23:00 11JAN22	CASH	0.00	CASH	13JAN22
R.O. OPENED		READY	OPTIONS: DLR:P250 ENG:79687791 TRN:S1037837				
11JAN22		13JAN22					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

SHOULD BE REPLACED. P&A ALL PARTS AND WAITING ON CUSTOMER APPROVAL. CUSTOMER HAD APPROVED THE REPAIRS. GOT PULLED OFF OF JOB. TECH 2560 DRAINED POWER STEERING AND OIL WAS VERY WATERY, DID A POWER STEERING FLUID FLUSH BEFORE REPLACING THE GEARBOX TO GET MOST OF THE OLD OIL OUT. REPLACED THE GEARBOX. PUT NEW OIL IN IT. SET THE POPPETS. STEERS FINE NOW.

C CUSTOMER REQUEST TO CLEAR FAULT CODES, SHOULD BE VOLTAGE RELATED
 ENG CUSTOMER REQUEST TO CLEAR FAULT CODES
 2181 C
 2560 C

	755.25	755.25
TECH TECHNOLOGY FEE	50.00	50.00
1 4307226CUM VALVE-PRESSURE RELIEF	162.31	137.42
1 2897581CUM SENSOR-FUEL PRESSURE	184.97	156.60
1 4984382CUM SEAL-PRESURE RELIEF PX8	9.25	7.83
1 4720 14 OZ PENRAY NC UL VOC BRK CLNR	2.38	2.38

636093 2181 1-11-22 CUSTOMER REQUESTED TO HAVE THE CODES CHECKED. HOOKED UP TO THE ENGINE AND CHECKED THE FAULT CODES. CHECKED AND FOUND THAT THE ONLY CODE THAT WAS ACTIVE WAS CODE 5383 FOR DPF ASH LOAD PERCENT. HAD SERVICE WRITER CALL CUSTOMER TO VERIFY THAT THE DPF AND DOC HAVEN'T BEEN CLEANED RECENTLY. CUSTOMER REQUESTED TO HAVE THE DPF AND DOC PULLED AND CLEANED. P&A ALL PARTS AND GOT APPROVAL. TECH 2560 PULLED TRUCK INSIDE THE SHOP. CONNECTED CUMMINS INSITE TO RESET THE AFTER TREATMENT AND CHECKED CODES TO VERIFY THE CODES AND HAS A CODE FOR THE FUEL RAIL METERING PRESSURE SENSOR ABNORMAL. WENT THRU TROUBLE SHOOTING AND INSPECTED THE CIRCUIT ON THE FUEL RAIL PRESSURE SENSOR AND IT WAS OK. NEXT STEP SAID TO REPLACE THE FUEL RAIL PRESSURE SENSOR BUT FROM EXPERIENCE I HAVE SEEN BEFORE WHERE THE FUEL RAIL PRESSURE RELIEF VALVE CAN CAUSE THIS EVEN THOUGH ITS NOT ON THE TROUBLESHOOTING. REMOVED THE BANJO BOLT OFF THE PRESSURE RELIEF VALVE AND RAN THE TRUCK AND THE PRESSURE RELIEF VALVE IS JUST POURING OUT LIKE ITS NOTHING. DID A INJECTOR PERFORMANCE TEST AND PRESSURE IS GOOD. RECOMMEND REPLACING THE FUEL RAIL PRESSURE RELIEF VALVE AND THE PRESSURE SENSOR SINCE THEY

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER
 The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

LOT LOCATION:
 CUSTOMER #: 129604
 UNIT# 14

169933

Peterbilt of Utah

INVOICE

1910 South 5500 West
 Salt Lake City, Utah 84104

BLUE ROCK LLC
 47 W FIRECLAY AVE APT 326
 MURRAY, UT 84107
 HOME: 801-699-3149 CONT: 801-699-3149

PAGE 3

P.O. Box 27634
 Salt Lake City, Utah 84127
 Phone (801) 486-8781

BUS: CELL: SERVICE ADVISOR: 1033 CORY LEONARD

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
CREAM	14	KENWORTH W900	1XKWD49X9EJ412350		636093/636093	T14

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP13 DD			23:00 11JAN22	CASH	0.00	CASH	13JAN22

R.O. OPENED	READY	OPTIONS:
11JAN22	13JAN22	DLR:P250 ENG:79687791 TRN:S1037837

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

BOTH ARE STILL ORIGINAL. GOING BACK TO THE DPF AND DOC DOUBLE CHECKED THE WORK FROM PREVIOUS TECH, WENT INTO THE REGEN HISTORY AND THE PRESSURE ARE ACTUALLY LOW AT 2.6 RESETTING THE SOOT LEVEL AND DOING A REGEN SHOULD JUST BE OK. DPF AND DOC DOES NOT HAVE TO BE DROPPED THE CODE ITS THROWING ITS JUST A SERVICE ADVISE NOT A ACTUAL PROBLEM FROM DPF PRESSURE. THE ACTUAL CHECK ENGINE LIGHT PROBLEM IS THE FUEL PROBLEM. P&A PARTS AND ADVISED FOREMAN. GOT THE OK. REPLACED THE FUEL RAIL PRESSURE SENSOR AND THE PRESSURE RELIEF VALVE. CONNECTED CUMMINS AGAIN CLEARED CODES. DID A PARKED REGEN TO VERIFY REPAIRS. NO MORE CHECK ENGINE LIGHT COMES ON. REPAIR COMPLETE.

MISC ENVIRONMENTAL FEE	C					25.00	25.00
------------------------	---	--	--	--	--	-------	-------

EST: 0.00 11JAN22 14:03 SA: 1033

CONTACT:

POWER STEERING INOP
 INTERMITTENTLY

PETERBILT "TRUCKCARE"
 (800)473-8372
 24 HOUR EMERGENCY ROADSIDE SERVICE
 WWW.PETERBILT.COM

DESCRIPTION	TOTALS
LABOR AMOUNT	1550.25
PARTS AMOUNT	1228.32
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	237.53
TOTAL CHARGES	3016.10
LESS INSURANCE	0.00
SALES TAX	229.22
PLEASE PAY THIS AMOUNT	3245.32

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

CUSTOMER COPY