Mason Diesel Service

P.O. Box 208 MM 4 Highway 24 Aurora, UT 84620 435-529-7477

Invoice

Date	Invoice #
1/8/2024	174123

Bill To	
Aftermath Trucking	
Mason Dies	
E. J. Hox 208	

lavoice

P.O. No.	Terms	Due Date	Rep	Unit #		Mileage		
		1/8/2024 Description		22		1,317,941		
Item				Qty	Rate	Amount		
vi ciliani de	9							
Labor	Labor			2.5	90.00	225.00T		
Hasor D		fuel filters				4930530		
	Replace	NOX sensor			AND THE PROPERTY OF	3 6 3 3 3 5 6		
		WIF sensor	an planet of the property of the soft			to see the		
	Replace	fan control valv	е					
				Responding to		ing.		
FG FF5825NN	Fuel filte	er		1	62.72	62.721		
10% discount	10% cus	stomer discount			-10.00%	-6.27		
FS 19727	Fuel filte			1	28.06	28.06T		
10% discount	10% cus	stomer discount			-10.00%	-2.81		
CUM 3687930R	V NOV.		gi na nasalika malikadilan			75 007		
PB 103111DVC		nsor / Recon		HATE HAND	618.11	618.117		
PB G90-6047	Control Control Control	d / fan control			91.82	91.82T		
. 2 000,001,	Sales Ta		100000000000000000000000000000000000000		133.96 6.45%	133.96T 74.21		
	32.55				0.45%	19.21		
						1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1		
si '\$1'						27.2		
A COSC L						1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
						M		

EUM 3687930FX FF 403011DVC

Total

1,224.80

Mason Diesel Service

P.O. Box 208 MM 4 Highway 24 Aurora, UT 84620 435-529-7477

Bill To	
Aftermath Trucking	

Invoice

Date	Invoice #
1/19/2024	174248

P.O. No.	Т	erms Due Date Rep		Rep	Unit	#	Mileage		
	e majering		1/19/2024		22				
Item			Descriptio	n	Qty	Rate	e Amount		
Labor		Found bo	eater/ac proble oth heater actu actuators and	lators bad	1.5	3	90.00	135.00T	
PDC 2378 PB:5\$013997	3 Sec. 13	Actuator Act		200-01S	1 1 1	17	95.76 75.18 45%		
. 3 . 3.j.									
	[4]							og. Nai	

Total \$432.12

CMC TIRE - SALINA 540 W MAIN ST SALINA UT 84654 435-359-0025

WORK ORDER #	70017752

PAGE:

Terminal ID: *****240 _____ 8:37 AM 2/21/24

US DEBIT - INSERT AID: A0000000980840 ACCT #: 7660

CREDIT SALE

UID: 405241375097 REF #: 2382 TH TRUCKING BATCH #: 476 AUTH #: 083759 OUNT

DESCRIPTION : _____

\$1384.84

TAX

AMOUNT

\$1384.84

INSTALLED NEW FRONTS ON UNIT# 22

TOTAL

APPROVED

ARQC - 4A2891E7E562B010

REMIT TO: CMC TIRE 9 S WASHINGTON ST SUITE #301

SPOKANE, WA 99201

SHIP TO: SERVICE ON 02/21/24

DONE BY CMC

SALINA UT

84654

\$0.00 9/B,R PO NUMBER: 22 0 0591 EASTERDAY

84642

/21/24

LICENSE: A021282 UT MILEAGE: 1336007 Fleet ID 0

1

DUE: 02/21/24

OUCTONER CORV	DESCRIPTION	QUANTITY	PRICE EXTE	NSION
CUSTOMER COPY	C SHOP SUPPLIES - SHOP	1	8.00	8.00
ric\n#:	MOUNT/MOUNT - MEDIUM TRUCK	2	30.00	60.00
VSTK	VALVE STEM BRASS - MEDIUM TRUC	К 2	8.95	17.90
06697	11R22.5 H-MICHELIN XLINE ENER	Z 2 ET: 29.3	718.00	1494.78
STFEE	STATE TIRE FEE	2	1.00	2.00
REJECT	REJECTED CASING	-2	100.00	-200.00

TOTAL UNITS: 2.00 1261.90 MERCHANDISE: LABOR: 60.00 2.00 OTHER: F.E.T.: 58.78 87.67 SALES TAX:

WORK ORDER TOTAL: 1470.35

********THIS IS NOT AN INVOICE****** ******DO NOT PAY FROM THIS FORM******

Customer	Signature	:	
Printed N	Name:		



305 W Industrial Park Dr. S. Salina, UT 84654

PH: (435) 529-2240 www.KenworthSalesCo.com Invoice: 00805W6196

Date / Hour: 3/6/2024 12:20:28PM

Repair Order: 6196 Customer: 1001

Branch: SALINA Total Invoice: \$ 5,623.56

Cash

Page 1 of 2

Bill To:

AFTERMATH TRUCKING LLC

Ship To: AFTERMATH TRUCKING LLC

. UT

. UT

Customer P/O

Open Date: 03/05/2024

Completion Date: 03/06/2024

Department: Service

Salesperson:

Unit Number: 22-231338

Add User: MAllred

Model Year: 2014

Make/Model: Peterbilt

Type: Service

VIN: 1XPXD49X5ED231338

Meter: 1341039 Miles

Task: 1 **ENG/CUMMIN ENGINE CUMMINS**

Complaint: CHECK AND REPAIR FREQUENT REGENS.

Correction: 3/5/2024 5:01:46 PM 190056 HOOK UP COMPUTER NO FAULT CODES FOR DPF. I CHECKED REGEN HISTORY HAS FREQUENT REGENS AND HIGH PRESSURES. I RECOMMENDED TO REPLACE DPF. GOT APPROVAL. REMOVED STEPS AND REMOVED DOC AND DPF. REPLACED DPF AND CLEANED DOC. DID DISCONNECTED SNAP TEST NO EXCESSIVE BLACK SMOKE. PUT BACK TOGETHER WITH NEW GASKETS AND CLAMPS. RESET AFTER TREATMENT MAINTENANCE AND INSULATION IN ECM. RAN TRUCK TO WARM IT UP AND RAN IPT TEST #6 FUEL INJECTOR FAILED NEEDS REPLACED. REMOVED VALVE COVER AND REPLACED #6 FUEL

INJECTOR AND CONNECTOR. PUT BACK TOGETHER. HOOKED UP COMPUTER AND RESET #6 INJECTOR IN ECM.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	2866337CUM	GASKET, AFM DEVICE	EA	1.0	\$14.69	\$14.69
	287216100 D	INJECTOR-MONARCH BLACK XPI ISX 11.9	EA	1.0	\$312.50	\$312.50
	2880215CUM	GASKET, AFM DEVICE	EA	1.0	\$19.08	\$19.08
	5579295CUM	KIT, PARTICULATE FILTER	EA	1.0	\$2,709.13	\$2,709.13
	5579419PXCUM	KIT, INJECTOR	EA	1.0		\$1,440,48
	287216100 D	INJECTOR-MONARCH BLACK XPI ISX 11.9	EA	-1.0	\$312.50	\$(312.50)
	Env Fee	Environmental Service Charge		1.0	\$10.00	\$10.00
		Task 1 Subtota	ıls	Parts:	\$4	1,183.38
				Core Chg:		\$312.50
				Core Ret:	(\$312.50)
				Labor:		\$800.00
				Miscellaneous:		\$10.00
				Task 1 Subtotals	\$4	,993.38

Task: 2 13-110003 Brakes - Anti-Lock System - Repair

Complaint: CHECK AND REPAIR ABS AND TRACTION CONTROL LIGHTS ARE ON.

Correction: 3/6/2024 11:01:43 AM 190056 HOOKED UP COMPUTER HAS FAULT CODES 4-1 FMI 1, 4-2 FMI 14, 5-3 FMI 2. FOR CODES 4-1,4-2 I PUSHED IN LEFT DRIVE AXLE WHEEL SPEED SENSOR. FOR CODE 5-3 I INSPECTED RIGHT DRIVE WHEEL SPEED SENSOR AND

FOUND BAD CONNECTOR. I REPAIRED CONNECTOR. CLEARED FAULT CODES AND ROAD TESTED.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
			Task 2 Subtotals	Parts:		\$0.00
				Labor:		\$160.00
				Task 2 Subtotals	,	\$160.00
Detail Tax I	nfo:	(Total Parts:	\$4	183.38
Salina Tr	UT Special Tax	\$28.92	Total	Core Charge:		
Salina UT	City Tax	\$57.86		Cole Charge.	Þ	312.50

Total Core Ret: \$(312.50) Sevier UT County Tax \$13.15 **Total Labor:** \$960.00 \$255.05 Utah UT State Tax **Total Miscellaneous:** \$354.98 \$10.00 Total: **Total Shop Supplies:** \$115.20

Department: Service

^{**} See Last Page for Invoice Total **



305 W Industrial Park Dr. S Salina, UT 84654

PH: (435) 529-2240 www.KenworthSalesCo.com Invoice: 00805W6196

Date / Hour: 3/6/2024 12:20:28PM

Repair Order: 6196 Customer: 1001

Branch: SALINA Total Invoice: \$ 5.623.56

Cash

Page 2 of 2

Bill To:

AFTERMATH TRUCKING LLC

Ship To: AFTERMATH TRUCKING LLC

, UT

, UT

Customer P/O:

Open Date: 03/05/2024

Completion Date: 03/06/2024

Salesperson

Add User: MAllred

Invoice Subtotal:

\$5,268.58

\$354.98

Total Invoice:

Total Tax:

\$5.623.56

Payment Method ***Cash***

Terms

Due Date

CASH

3/6/2024

Remit To-

Kenworth Sales Company, Inc - Salina

Dept. #001 PO Box 27088

Salt Lake City, UT 84127-0088

Paid With:

Amount Due: \$5,623.56

Amount Received:\$5,623,56

Chg Due: \$0.00

The customer ("Customer") acknowledges inspecting the repairs performed by Kenworth Sales Co., Inc. ("Seller") on Customer's equipment ("the Equipment") and accepts the 2.00 same in satisfaction of the repairs requested by Customer from Seller ("the Repairs"). As consideration for the Repairs Customer agrees to the following terms and conditions. Customer will pay the total amount due, together with a service charge of 1-3/4% per month (21% per annum) on all amounts remaining unpaid after the 10th of the month following receipt, with a minimum charge of \$15.00, and a daily storage fee of \$30.00 for each piece of Equipment remaining with Seller 30 days after 1) completion of authorized repairs or 2) cessation of repairs/service for any reason. Customer will pay all collection costs including a reasonable attorney's fee, and hereby waives all claims or rights to claim exemptions under applicable state laws. Customer grants Seller an express Repairman's Lien on the Equipment for the value of the parts and any services provided and warrants that no 3rd party holds a superior lien on the Equipment except as disclosed by Customer. Any warranties on the product(s) sold hereby are those of the manufacturer. Warranty claims must be submitted within 30 days of discovery of defect. Seller disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of the merchandise or services hereunder. Claims for adjustments or credits must be made within ten (10) days of the date of this document and must be accompanied by a complete copy of this document. Customer acknowledges that in the course of performing the Repairs, Seller may have connected the Equipment to Original Equipment Manufacturer ("OEM") approved electronic equipment, and that such tool may reset the operating parameters of the Equipment to OEM required settings. Customer accepts any and all risks that may occur in the event of a conflict between such original OEM settings and any post-production modifications made by Customer to the Equipment. Customer releases Seller from liability for any damages to the Equipment or its contents due to loss, theft, destruction, or causes other than gross negligence, and further releases Seller from liability for down time, damage to cargo, or other damage related to delays in completing the requested repairs and/or delay in obtaining parts.

O Cianatura	
Customer Signature	

B AND B TRUCK AND 20812 E 550Th COLONA IL 61241 309/793-0120

Invoice:

3231

Date:

3/11/2024

SALE

REF#: 00000006

Batch #: 068001 03/11/24

RRN: 434503253 14:21:51

Invoice #: 6 APPR CODE: 611161

*********9582

Chip **/** **Remit Payment To**

Primary

20812 East 550th Street

Colona, IL 61241

AMOUNT

\$4,856.30

Terms

h 1000 east

JT 84102-3908

er.com

ing

Due Date

Authorizer

Customer PO

Quantity

Unit #

Net 30

4/10/2024

Craig Casimir

22

Item

Description

Amount

Complaint: front power divider maybe?

Cause: came apart interally

Labor

Parts

Correction:

Transmission / Drive Shaft / drained front diff/power divider, pulled axles, drive line and divider .Cleaned housing, resealed and installed new power divider, reinstalled axles, drive line and filled with new fluid. - Completed: 3/11/2024

AXLE FLANGE GASKET

Parts reman diff

Parts

Oil Synthetic Gear Lb

6.00000

2.00000

40.00000

\$175.00 \$1,050.00

Rate

\$2.89 1.00000 \$2,998.95 \$2,998.95

\$6.85

Subtotal

\$274.00 \$4,328.73

\$5.78

Complaint: On test drive drug the trailer wires, replaced with new because old ones were damaged.

Cause: our mistake

(Inspection)

Labor Correction:

Electrical System / Wiring / replaced complete three way didn't have ends - Completed:

3/11/2024

Parts

15FOOT 3WAY

Parts Parts

Gladhand Serv - Blue Gladhand Emerg - Red

0.00000

1.00000

1.00000

\$0.00

\$0.00

\$0.00

\$0.00

1.00000 \$0.00

Subtotal

\$0.00

\$0.00

\$141.04

\$0.00

visa fee

1.00

\$141.04

MASON DIESEL 261 \$ 200 E AURORA, UT 84620 435-529-7477

25:2024 15:37:19

DEBIT CARD DEBIT SALE

Card # XXXXXXXXXXXXXX7660 Network: Chip Card: US DEBIT AID: A0000000980840 SEQ =. Batch #. Trans # Approval Code: 062035 TRANS ID: 384085804345671 Entry Method: Chip Read

Service

Invoice

Date	Invoice #				
3/25/2024	174897				

03 25 2024

ivoice

Invoice #

200 174897

to.

SALE AMOUNT

Mode:

\$618.13

Issuer - PIN Bypassed

THANK YOU

rms	Due Date	Rep	Unit #	Mileage
	3/25/2024		22	1,346,323
S MINISTER OF THE	Y USA TEXAL PROPERTY.		SEACH WAS ARRESTED TO THE SEACH OF THE SEACH	

CLICT DATE: DOD	Description	Qty	Rate	Amount	
CUSTOMER COPY	VIN ED231338				
Lason Dies	Labor	5	90.00	450-00T	
P.O. Box 208 MM 4 Highway 2-	Check and tighten front trailer axle bearings, change RH rear bearing		\$	invoice #	
PANIS -	to oil, Diagnose and repair ABS issues		21.37	Villea e	
BAT 06-240	Spindle nut / outer E7666	1	25.51	⁵⁴⁰ , 25.51T	
BAT 06-238	Spindle nut / inner E7664	1	14.08		
BAT 06-239	Axle lock washer E7665	1	19.75	19.75T	
Misc 1	small allen head lock screw	1	2.75	2.75T	
ABP 10045889	Wheel seal	1	27.86	27.86T	
STM 340 4195	Oil hubcap	1	33.72	33.72T	
80W-90 QT.	80W-90 QT. Bottle [2 lb.]	1	7.01	57.01T	
p1\14119\tovar\2	Sales Tax		6.45%	37.45	
1-1014 T 1 1624	1		21 %	1.1:2:	
DENNIN			**	villea: e	
		1			
	-			The training	
				1. 3 2. EAY	

F 1004: 669 \$37 M 640 4195 (85) 80W-80 QT.,

PATH A PARTICION ON A COST

Total :

\$618.13

When on

MASON DIESEL .11 S 200 E AURORA, UT 84620

09:53:55

013

3

9

999

000096

Chip Read

Issuer - PIN Verified

STAR

US DEBIT

XXXXXXXXXXXXX7660

A0000000980840

435-529-7477

05 07 2024 DEBIT CARD

DEBIT SALE

Card ∓

Debit Card Type: Network:

Chip Card: AID: SEQ ...

Batch =: Trans = Approval Code:

Entry Method: Mode:

SALE AMOUNT

\$527.33

Service

Invoice

Date	Invoice #
5/7/2024	175362

rms	rms Due Date		Unit #	Mileage		
	5/7/2024		22	1,360,095		

	Descriptio	n	Qty	Rate	•	Amount
VIN ED	231338					
Replace b Check an Replace l	oreather tube d repair lights eft windshield		4	(90.00	360.00T
Breather			1		16.02	16.02T
Bulb			1 1 5	;	30.99 0.87 1.00	30.99T 0.87T 5.00T
			1	1	882 97	82.50T 31.95
	Labor Check dif Replace t Check an Replace I Check wip Breather M3 LED F Bulb bolts, nuts	VIN ED231338 Labor Check differential leak Replace breather tube Check and repair lights Replace left windshield Check wipers Breather M3 LED Red lens	Labor Check differential leak Replace breather tube assembly Check and repair lights Replace left windshield Check wipers Breather M3 LED Red lens Bulb bolts, nuts, washers, Windshield / LH	VIN ED231338 Labor 4 Check differential leak Replace breather tube assembly Check and repair lights Replace left windshield Check wipers Breather 1 M3 LED Red lens 1 Bulb 1 bolts, nuts, washers, 5 Windshield / LH 1	Labor Check differential leak Replace breather tube assembly Check and repair lights Replace left windshield Check wipers Breather M3 LED Red lens Bulb bolts, nuts, washers, Windshield / LH 4 S 4 S 4 S 5 5 Windshield / LH	VIN ED231338 Labor

Total

\$527.33